

~~#28468~~  
#26455

# S

## hawver

### WELL COMPANY, INC.

#### WATER WELL DRILLING AND REPAIRING

P.O. BOX 266

DIAL 319-237-5341

FREDERICKSBURG, IOWA 50630

City of Clarksville  
Log of well drilled October, 1981

## LOG OF WELL

0'	to	10'	Topsoil and clay
10'	to	30'	Sand
30'	to	35'	Gravel and clay
35'	to	36'	Brown clay
36'	to	40'	Brown clay and limerock
40'	to	100'	Broken limerock
100'	to	120'	Brown clay and limerock
120'	to	130'	Broken limerock
130'	to	140'	Limerock and blue shale
140'	to	155'	Broken limerock and shale
155'	to	160'	Limerock-gray and brown
160'	to	195'	Gray limerock
195'	to	220'	Brown and gray limerock

755 gallons per minute was pumped with a drawdown of 2'½".